

User Manual for Portable Power Station

Thank you for choosing Portable Power Station SFMP. Please read the user manual carefully before using the Portable Power Station. Keep this user manual in a safe and proper place for your future reference.

Safety Notice

- Scorpion and their re-sellers are not responsible for your use of this products, or any damage of injuries you may cause or sustain as a result of it's usage.
- Do not modify, disassemble, open, drop, crush, puncture or shred this product.
- Keep away from open flame or sunlight to prevent heat build-up.
- Keep away from children and pets, this is NOT a toy.

Limited Warranty

This limited warranty shall last for (six) months from the date of original purchase, this limited warranty applies only due to the manufacturing defect and does not apply to any improper installation, unauthorized repair, alternation or modification of this product.


Included in the Box

- 1 x Portable Power Station
- 1 x User Manual
- 1 x Micro USB Cable

Specification

Model Number	: SFMP-V50A
Cell Type	: Li-polymer battery
Capacity	: 5200 mAh
Dimension	: 115mm x 59mm x 12mm
Weight	: 120 grams
Charging Time	: 3 ~ 4 hours
Input	: DC 5.0v / 2000mA
Output	: DC 5.0v / 1000mA

Product Layout



- ① LED Indicator
- ② ON/OFF Button
- ③ USB Output Port
- ④ Micro USB Input Port
- ⑤ Micro USB Cable

Indication of Light – Li-Po Charge Status

1-Solid Green Light	<25% (Charging is required)
2-Solid Green Light	25~50%
3-Solid Green Light	50~75%
4-Solid Green Light	75~100%

Charging the Power Station

Connect the included micro-USB cable to charge the Portable Power Station from the USB port on your computer or from a USB compatible wall charger. Each LED flashes and remains solid as its corresponding capacity has been reached. All LEDs remain solid when the unit is fully charged.

Charging your Device

Connect the USB cable included with your device to Portable Power Station USB Output port and press ON/OFF button to begin charging. When no connection is detected for more than 5 seconds, the Portable Power Station shuts off automatically.

Maintenance

- Do not store in a depleted state as the battery power cells can be damaged. Charge your Portable Power Station at least once every 3 months when not in use.
- Keep the unit dry. Avoid damp conditions and corrosive materials.
- Do not clean with harsh chemicals, soaps or detergents.



Scorpion Power System
www.scorpionsystem.com

**User Manual for
Portable Power Station**